

# Lead in School Drinking Water Report

## Balboa Elementary School



Date(s) collected: 2024-04-18

Date(s) analyzed: 2024-04-25, 2024-04-26

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
37810 4	Main Building	Sink - Multi-Compartment	Kitchen	2 of 4	Tap	left	98
37810 5	Main Building	Sink - Multi-Compartment	Kitchen	2 of 4	Tap	right	74
37810 3	Main Building	Pot Filler	Kitchen	1 of 4.	Tap	other	35
37811 3	Main Building	Sink	Room 110	1 of 1	Tap	left	19
37810 6	Main Building	Sink	Kitchen	3 of 4	Tap	center	14
37811 7	Main Building	Sink	Room 108	1 of 1	Tap	left	10
37815 8	Portable B 1992	Sink	Room B-101	1 of 1	Tap	center	10
37860 5	Main Building	Sink	Room 104	1 of 1	Tap	left	9
37864	Main	Sink	Room 113a	1 of 1	Tap	center	9

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
8	Building						
37861	Main Building	Sink	Room 131	1 of 1	Tap	left	8
37861	Main Building	Sink	Room 135	1 of 1	Tap	left	8
37815	Main Building	Sink	Room 137	1 of 1	Tap	left	6
37864	Portable D 1993	Sink	Room D-103	1 of 1	Tap	center	6
37814	Main Building	Sink	Room 136	1 of 1	Water Fountain	right	5
37815	Main Building	Sink	Room 138	1 of 1	Tap	left	5
37811	Main Building	Sink	Room 105	1 of 1	Tap	left	4
37815	Main Building	Sink	Room 137	1 of 1	Water Fountain	right	4
37860	Main Building	Sink	Room 101	1 of 1	Tap	left	4
37810	Main Building	Sink	Kitchen	4 of 4	Sprayer	center	3
37810	Main Building	Fountain	Gym/Commons	1 of 1	Water Fountain	left	3
37811	Main Building	Sink	Room 107	1 of 1	Tap	left	3
37814	Main Building	Sink	Room 135	1 of 1	Water Fountain	right	3
37814	Main Building	Sink	Room 136	1 of 1	Tap	left	3
37815	Main Building	Sink	Room 138	1 of 1	Water Fountain	right	3
37815	Portable	Sink	Room A-102	1 of 1	Tap	left	3

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
4	A 1993						
37815	Portable A 1993	Sink	Room A-102	1 of 1	Water Fountain	right	3
37860	Main Building 1	Sink	Room 106	1 of 1	Tap	left	3
37860	Main Building 3	Sink	Room 103	1 of 1	Tap	left	3
37861	Main Building 4	Sink	Room 131	1 of 1	Water Fountain	right	3
37861	Main Building 6	Sink	Room 133	1 of 1	Water Fountain	right	3
37864	Portable B 1992	Sink	Room B-103	1 of 1	Tap	center	3
37815	Portable A 1993	Sink	Room A-104	1 of 1	Tap	left	2
37860	Main Building 9	Sink	Room 102	1 of 1	Tap	left	2
37861	Main Building 2	Fountain	Hallway Next To Room 132	2 of 2. Fountain closer to girls restroom	Water Fountain	left	2
37861	Main Building 5	Sink	Room 133	1 of 1	Tap	left	2
37861	Main Building 8	Sink	Room 134	1 of 1	Water Fountain	right	2
37864	Portable C 1993	Sink	Room C-101	1 of 1	Tap	center	2
37860	Main Building 6	Sink	Room 104	1 of 1	Water Fountain	right	1
37861	Main Building 1	Fountain	Hallway Next To Room 132	1 of 2. Fountain	Water Fountain	left	1

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
				closer to boys restroom	in		
378617	Main Building	Sink	Room 134	1 of 1	Tap	left	1
378109	Main Building	Fountain with Bottle Filler	Hallway Across From Library	1 of 1	Water Bottle Filler	center	<1
378110	Main Building	Fountain with Bottle Filler	Hallway Across From Library	1 of 1	Water Fountain	right	<1
378111	Main Building	Fountain	Hallway Across From Library	1 of 1	Water Fountain	left	<1
378112	Main Building	Sink - Multi-Compartment	Room 109 Staff Lounge	1 of 1	Tap	center	<1
378114	Main Building	Sink	Room 110	1 of 1	Water Fountain	right	<1
378116	Main Building	Sink	Room 107	1 of 1	Water Fountain	right	<1
378118	Main Building	Sink	Room 108	1 of 1	Water Fountain	right	<1
378157	Portable A 1993	Sink	Room A-104	1 of 1	Water Fountain	right	<1
378159	Portable B 1992	Sink	Room B-101	1 of 1	Water Fountain	right	<1
378600	Main Building	Sink	Room 105	1 of 1	Water Fountain	right	<1
378602	Main Building	Sink	Room 106	1 of 1	Water Fountain	right	<1

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
378604	Main Building	Sink	Room 103	1 of 1	Water Fountain	right	<1
378608	Main Building	Sink	Room 101	1 of 1	Water Fountain	right	<1
378610	Main Building	Sink	Room 102	1 of 1	Water Fountain	right	<1
378641	Portable B 1992	Sink	Room B-103	1 of 1	Water Fountain	left	<1
378643	Portable C 1993	Sink	Room C-101	1 of 1	Water Fountain	left	<1
378644	Portable C 1993	Sink	Room C-103	1 of 1	Tap	center	<1
378645	Portable C 1993	Sink	Room C-103	1 of 1	Water Fountain	right	<1
378647	Portable D 1993	Sink	Room D-103	1 of 1	Water Fountain	left	<1

#### EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: [leadfreekids@doh.wa.gov](mailto:leadfreekids@doh.wa.gov)