

# Lead in School Drinking Water Report

## Indian Trail Elementary School



Date(s) collected: 2024-05-04

Date(s) analyzed: 2024-05-23, 2024-05-30

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
378743	Main Building	Sink	Kitchen	3 of 4	Water Bottle Filler	left	56
378747	Main Building	Sink	Room 137	1 of 1	Tap	center	43
378756	Main Building Annex 1 1967	Sink	Room A102	1 of 1	Water Fountain	right	14
378742	Main Building	Sink	Kitchen	3 of 4	Tap	center	10
378749	Main Building Annex 1 1967	Sink	Room A108	1 of 1	Water Fountain	right	9
388183	Main Building	Sink	Room 105	1 of 1	Tap	left	9

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
388194	Main Building	Sink	Room 120	1 of 1	Tap	left	9
388187	Main Building	Sink	Room 104	1 of 1	Tap	left	8
388206	Main Building	Sink	Room 109	1 of 1	Tap	left	8
388210	Main Building	Sink	Room 108	1 of 1	Tap	left	8
378752	Main Building Annex 1 1967	Fountain	Hallway. Next To Room A107	1 of 2	Water Fountain	right	7
378758	Main Building Annex 1 1967	Sink	Room A101	1 of 1	Water Fountain	right	7
388195	Main Building	Sink	Room 101	1 of 1	Tap	left	7
388218	Main Building	Sink	Room 106	1 of 1	Tap	left	7
378751	Main Building Annex 1 1967	Fountain	Hallway. Next To Room A107	1 of 2	Water Fountain	left	6
388186	Main Building	Sink	Room 122	1 of 1	Tap	left	6
388191	Main Building	Sink	Room 102	1 of 1	Tap	left	6
388198	Main Building	Sink	Room 121	1 of 1	Tap	left	6
388214	Main Building	Sink	Room 107	1 of 1	Tap	left	6
378755	Main Building Annex 1 1967	Sink	Room A102	1 of 1	Tap	left	5
388190	Main Building	Sink	Room 123	1 of 1	Tap	left	5

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
	Building						
388211	Portable C 1993	Sink	Room C102	1 of 1	Tap	center	5
378748	Main Building Annex 1 1967	Sink	Room A108	1 of 1	Tap	left	4
388181	Main Building	Sink	Room 106	1 of 1	Water Fountain	right	4
388207	Portable C 1993	Sink	Room C101	1 of 1	Tap	center	4
378259	Main Building	Sink - Multi-Compartment	Kitchen	2 of 4	Tap	left	3
378740	Main Building	Sink - Multi-Compartment	Kitchen	2 of 4	Tap	center	3
378741	Main Building	Sink - Multi-Compartment	Kitchen	2 of 4	Tap	right	3
388184	Main Building	Sink	Staff Room 126	1 of 1	Tap	center	3
388212	Main Building	Sink	Room 108	1 of 1	Water Fountain	right	3
378757	Main Building Annex 1 1967	Sink	Room A101	1 of 1	Tap	left	2
378759	Main Building	Sink	Nurses Office	1 of 1	Tap	center	2
388185	Main Building	Sink	Room 105	1 of 1	Water Fountain	right	2
388188	Main Building	Sink	Room 122	1 of 1	Water Fountain	right	2
388189	Main Building	Sink	Room 104	1 of 1	Water Fountain	right	2
388193	Main Building	Sink	Room 102	1 of 1	Water Fountain	right	2
388196	Main Building	Sink	Room 120	1 of 1	Water Fountain	right	2

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
388199	Portable B 1992	Sink	Room B101	1 of 1	Tap	center	2
388205	Portable B 1992	Sink	Room B102	1 of 1	Water Fountain	left	2
388208	Main Building	Sink	Room 109	1 of 1	Water Fountain	right	2
378257	Main Building	Sink	Kitchen	1 of 4	Tap	center	1
388200	Main Building	Sink	Room 121	1 of 1	Water Fountain	right	1
388216	Main Building	Sink	Room 107	1 of 1	Water Fountain	right	1
378258	Main Building	Sink	Kitchen	1 of 4	Sprayer	center	<1
378744	Main Building	Sink	Kitchen	4 of 4. Dish washing sink	Sprayer	center	<1
378745	Main Building	Fountain with Bottle Filler	Next To Room 137	1 of 1	Water Bottle Filler	center	<1
378746	Main Building	Fountain with Bottle Filler	Next To Room 137	1 of 1	Water Fountain	right	<1
378750	Main Building Annex 1 1967	Sink	Room A109	1 of 1	Tap	left	<1
378753	Main Building Annex 1 1967	Fountain with Bottle Filler	Hallway	2 of 2. Next to bathroom A103	Water Bottle Filler	center	<1
378754	Main Building Annex 1 1967	Fountain with Bottle Filler	Hallway. Next To Bathroom A103	2 of 2	Water Fountain	right	<1
388180	Main Building	Fountain with Bottle Filler	Main Entrance Foyer.	1 of 1	Water Bottle Filler	center	<1

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
			Across From Room 127				
388182	Main Building	Fountain with Bottle Filler	Main Entrance Foyer	1 of 1	Water Fountain	right	<1
388192	Main Building	Sink	Room 123	1 of 1	Water Fountain	right	<1
388197	Main Building	Sink	Room 101	1 of 1	Water Fountain	right	<1
388201	Portable B 1992	Sink	Room B101	1 of 1	Water Fountain	left	<1
388202	Main Building	Fountain with Bottle Filler	Next To Staff Restroom 112	1 of 1	Water Bottle Filler	center	<1
388203	Portable B 1992	Sink	Room B102	1 of 1	Tap	center	<1
388204	Main Building	Fountain with Bottle Filler	Next To Staff Restroom 112	1 of 1	Water Fountain	right	<1
388209	Portable C 1993	Sink	Room C101	1 of 1	Water Fountain	left	<1
388213	Portable C 1993	Sink	Room C102	1 of 1	Water Fountain	right	<1

#### EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: [leadfreekids@doh.wa.gov](mailto:leadfreekids@doh.wa.gov)