

# Lead in School Drinking Water Report

## Longfellow Elementary School



Date(s) collected: 2024-04-20  
Date(s) analyzed: 2024-05-06

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
378216	Main Building	Sink	Kitchen	4 of 4	Tap	center	304*
378665	Main Building	Sink	Room 113	1 of 1	Tap	left	46
378217	Main Building	Sink	Cafeteria Sink	1 of 1	Tap	center	34
378703	Main Building	Sink	Room 148. Music Room	1 of 1	Tap	center	26
378676	Main Building	Sink	Room 123	1 of 1	Tap	left	18
378219	Main Building	Sink	Room 145	2 of 2	Tap	center	17
378704	Main Building	Sink	Room 201	1 of 1	Tap	left	16
378710	Main Building	Sink	Room 207	1 of 1	Tap	left	11

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
378712	Main Building	Sink	Room 209	1 of 1	Tap	left	11
378179	Main Building	Sink	Room 107	1 of 1	Tap	left	10
378717	Main Building	Sink	Room 215	1 of 1	Tap	left	10
378667	Main Building	Sink	Room 115	1 of 1	Tap	left	9
378173	Main Building	Sink	Room 101	1 of 1	Tap	left	8
378221	Main Building	Sink	Room 219	1 of 1	Tap	left	8
378701	Main Building	Sink	Nurses Office	1 of 1	Tap	center	8
378719	Main Building	Sink	Room 217	1 of 1	Tap	left	8
378666	Main Building	Sink	Room 113	1 of 1	Water Fountain	right	7
378671	Main Building	Sink	Room 119	1 of 1	Tap	left	7
378177	Main Building	Sink	Room 105	1 of 1	Tap	left	6
378212	Main Building	Sink - Multi-Compartment	Kitchen	1 of 4	Tap	left	6
378675	Main Building	Sink - Multi-Compartment	Staff Lounge	1 of 1	Tap	center	6
378661	Main Building	Sink	Room 109	1 of 1	Tap	left	5
378668	Main Building	Sink	Room 115	1 of 1	Water Fountain	right	5
378669	Main Building	Sink	Room 117	1 of 1	Tap	left	5
378670	Main Building	Sink	Room 117	1 of 1	Water Fountain	right	5
378674	Main Building	Sink	Room 121	1 of 1	Water Fountain	right	5

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
378677	Main Building	Sink	Room 123	1 of 1	Water Fountain	right	5
378679	Main Building	Sink	Room 127	1 of 1	Tap	left	5
378711	Main Building	Sink	Room 207	1 of 1	Water Fountain	right	5
378175	Main Building	Sink	Room 103	1 of 1	Tap	left	4
378176	Main Building	Sink	Room 103	1 of 1	Water Fountain	right	4
378178	Main Building	Sink	Room 105	1 of 1	Water Fountain	right	4
378218	Main Building	Sink - Multi-Compartment	Room 145. Art Room	1 of 2	Tap	center	4
378660	Main Building	Sink	Room 107	1 of 1	Water Fountain	right	4
378662	Main Building	Sink	Room 109	1 of 1	Water Fountain	right	4
378672	Main Building	Sink	Room 119	1 of 1	Water Fountain	right	4
378678	Main Building	Fountain	In Between Restrooms Across From Room 123	1 of 1	Water Fountain	right	4
378706	Main Building	Sink	Room 203	1 of 1	Tap	left	4
378708	Main Building	Sink	Room 205	1 of 1	Tap	left	4
378715	Main Building	Sink	Room 211	1 of 1	Tap	left	4
378174	Main Building	Sink	Room 101	1 of 1	Water Fountain	right	3
378200	Main Building	Sink	Room 127	1 of 1	Water Fountain	right	3
378203	Main Building	Sink	Room 133	1 of 1	Tap	left	3

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
378204	Main Building	Sink	Room 133	1 of 1	Water Fountain	right	3
378213	Main Building	Sink - Multi-Compartment	Kitchen	1 of 4	Tap	right	3
378215	Main Building	Sink - Multi-Compartment	Kitchen	3 of 4	Tap	center	3
378220	Main Building	Sink	Room 217	1 of 1	Water Fountain	right	3
378222	Main Building	Sink	Room 219	1 of 1	Water Fountain	right	3
378673	Main Building	Sink	Room 121	1 of 1	Tap	left	3
378705	Main Building	Sink	Room 201	1 of 1	Water Fountain	right	3
378713	Main Building	Sink	Room 209	1 of 1	Water Fountain	right	3
378714	Main Building	Fountain	Across From Room 209	1 of 1	Water Fountain	right	3
378718	Main Building	Sink	Room 215	1 of 1	Water Fountain	right	3
378202	Main Building	Sink	Room 129	1 of 1	Water Fountain	right	2
378205	Main Building	Sink	Room 135	1 of 1	Tap	left	2
378209	Main Building	Fountain	Gym	1 of 1	Water Fountain	right	2
378663	Main Building	Sink	Room 111	1 of 1	Tap	left	2
378664	Main Building	Sink	Room 111	1 of 1	Water Fountain	right	2
378700	Main Building	Fountain	Across From Nurses Office In Between Restrooms	1 of 1	Water Fountain	right	2

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
378707	Main Building	Sink	Room 203	1 of 1	Water Fountain	right	2
378709	Main Building	Sink	Room 205	1 of 1	Water Fountain	right	2
378716	Main Building	Sink	Room 211	1 of 1	Water Fountain	right	2
378207	Main Building	Sink	Room 137	1 of 1	Tap	left	1
378214	Main Building	Sink	Kitchen	2 of 4	Sprayer	center	1
378201	Main Building	Sink	Room 129	1 of 1	Tap	left	<1
378206	Main Building	Sink	Room 135	1 of 1	Water Fountain	right	<1
378208	Main Building	Sink	Room 137	1 of 1	Water Fountain	right	<1
378210	Main Building	Fountain with Bottle Filler	Multi Purpose Room/ Cafeteria	1 of 1	Water Bottle Filler	center	<1
378211	Main Building	Fountain with Bottle Filler	Cafeteria	1 of 1	Water Fountain	right	<1
378223	Portable 2014	Sink	A-101	1 of 1	Tap	center	<1
378224	Portable 2014	Sink	A-102	1 of 1	Tap	center	<1

#### EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: [leadfreekids@doh.wa.gov](mailto:leadfreekids@doh.wa.gov)

*\*Re-testing due to potential anomaly.*