

Lead in School Drinking Water Report

Browne Elementary School



Date(s) collected: 2024-04-19

Date(s) analyzed: 2024-04-25, 2024-04-29, 2024-04-30

| Sample ID | Building Name | Fixture Housing Type | Fixture Location | Fixture Location Details | Fixture Type | Fixture Position | Lead Test Result (ppb) |
|-----------|----------------------|--------------------------|---------------------|--------------------------|--------------|------------------|------------------------|
| 378138 | Main Building - 2218 | Sink | Room 121 | 1 of 1 | Tap | left | 6 |
| 378651 | Main Building - 2218 | Sink - Multi-Compartment | Kitchen | 1 of 3 | Tap | right | 6 |
| 378631 | Main Building - 2218 | Sink | Room 209 | 1 of 1 | Tap | left | 4 |
| 378633 | Main Building - 2218 | Sink | Room 211 | 1 of 1 | Tap | left | 4 |
| 378171 | Main Building - 2218 | Sink | Room 131 Music Room | 1 of 1 | Tap | center | 3 |
| 378624 | Main Building | Sink | Library Office | 1 of 1 | Tap | center | 3 |

| Sample ID | Building Name | Fixture Housing Type | Fixture Location | Fixture Location Details | Fixture Type | Fixture Position | Lead Test Result (ppb) |
|-----------|----------------------|--------------------------|------------------|--------------------------|----------------|------------------|------------------------|
| | - 2218 | | Room 201b | | | | |
| 378650 | Main Building - 2218 | Sink - Multi-Compartment | Kitchen | 1 of 3 | Tap | left | 3 |
| 378653 | Main Building - 2218 | Sink | Kitchen | 3 of 3 | Tap | center | 3 |
| 378130 | Main Building - 2218 | Sink | Room 113 | 1 of 1 | Tap | left | 2 |
| 378132 | Main Building - 2218 | Sink | Room 115 | 1 of 1 | Tap | left | 2 |
| 378136 | Main Building - 2218 | Sink | Room 119 | Room 119 | Tap | left | 2 |
| 378161 | Main Building - 2218 | Sink | Room 219 | 1 of 1 | Tap | left | 2 |
| 378167 | Main Building - 2218 | Sink | Room 225 | 1 of 1 | Tap | left | 2 |
| 378620 | Main Building - 2218 | Sink | Room 123 | 1 of 1 | Tap | left | 2 |
| 378629 | Main Building - 2218 | Sink | Room 207 | 2 of 2 | Tap | left | 2 |
| 378630 | Main Building - 2218 | Sink | Room 207 | 2 of 2 | Water Fountain | right | 2 |
| 378652 | Main Building - 2218 | Sink | Kitchen | 2 of 3 | Sprayer | center | 2 |
| 378656 | Main Building - 2218 | Sink | Health Room 104 | 1 of 1 | Tap | center | 2 |
| 378657 | Main | Sink | Staff Room | 1 of 1 | Tap | center | 2 |

| Sample ID | Building Name | Fixture Housing Type | Fixture Location | Fixture Location Details | Fixture Type | Fixture Position | Lead Test Result (ppb) |
|-----------|----------------------|----------------------|------------------|-----------------------------|----------------|------------------|------------------------|
| | Building - 2218 | | 108c | | | | |
| 378124 | Main Building - 2218 | Sink | Room 107 | 1 of 1 | Tap | left | 1 |
| 378128 | Main Building - 2218 | Sink | Room 111 | 1 of 1 | Tap | left | 1 |
| 378134 | Main Building - 2218 | Sink | Room 117 | 1 of 1 | Tap | left | 1 |
| 378163 | Main Building - 2218 | Sink | Room 221 | 1 of 1 | Tap | left | 1 |
| 378169 | Main Building - 2218 | Sink | Room 227 | 1 of 1 | Tap | left | 1 |
| 378625 | Main Building - 2218 | Sink | Room 205 | 1 of 1 | Tap | left | 1 |
| 378626 | Main Building - 2218 | Sink | Room 205 | 1 of 1 | Water Fountain | right | 1 |
| 378627 | Main Building - 2218 | Sink | Room 207 | 1 of 2. Sink closer to door | Tap | left | 1 |
| 378635 | Main Building - 2218 | Sink | Room 213 | 1 of 1 | Tap | left | 1 |
| 378637 | Main Building - 2218 | Sink | Room 215 | 1 of 1 | Tap | left | 1 |
| 378639 | Main Building - 2218 | Sink | Room 217 | 1 of 1 | Tap | left | 1 |
| 378658 | Main Building | Sink | Room 101 | 1 of 1 | Tap | left | 1 |

| Sample ID | Building Name | Fixture Housing Type | Fixture Location | Fixture Location Details | Fixture Type | Fixture Position | Lead Test Result (ppb) |
|-----------|----------------------|----------------------|------------------|--------------------------|----------------|------------------|------------------------|
| | - 2218 | | | | | | |
| 378120 | Main Building - 2218 | Sink | Room 103 | 1 of 1 | Tap | left | <1 |
| 378121 | Main Building - 2218 | Sink | Room 103 | 1 of 1 | Water Fountain | right | <1 |
| 378122 | Main Building - 2218 | Sink | Room 105 | 1 of 1 | Tap | left | <1 |
| 378123 | Main Building - 2218 | Sink | Room 105 | 1 of 1 | Water Fountain | right | <1 |
| 378125 | Main Building - 2218 | Sink | Room 107 | 1 of 1 | Water Fountain | right | <1 |
| 378126 | Main Building - 2218 | Sink | Room 109 | 1 of 1 | Tap | left | <1 |
| 378127 | Main Building - 2218 | Sink | Room 109 | 1 of 1 | Water Fountain | right | <1 |
| 378129 | Main Building - 2218 | Sink | Room 111 | 1 of 1 | Water Fountain | right | <1 |
| 378131 | Main Building - 2218 | Sink | Room 113 | 1 of 1 | Water Fountain | right | <1 |
| 378133 | Main Building - 2218 | Sink | Room 115 | 1 of 1 | Water Fountain | right | <1 |
| 378135 | Main Building - 2218 | Sink | Room 117 | 1 of 1 | Water Fountain | right | <1 |
| 378137 | Main Building - 2218 | Sink | Room 119 | 1 of 1 | Water Fountain | right | <1 |
| 378139 | Main | Sink | Room 121 | 1 of 1 | Water | right | <1 |

| Sample ID | Building Name | Fixture Housing Type | Fixture Location | Fixture Location Details | Fixture Type | Fixture Position | Lead Test Result (ppb) |
|-----------|----------------------|------------------------|--------------------------------------|--------------------------|----------------|------------------|------------------------|
| | Building - 2218 | | | | Fountain | | |
| 378160 | Main Building - 2218 | Sink | Room 217 | 1 of 1 | Water Fountain | right | <1 |
| 378162 | Main Building - 2218 | Sink | Room 219 | 1 of 1 | Water Fountain | right | <1 |
| 378164 | Main Building - 2218 | Sink | Room 221 | 1 of 1 | Water Fountain | right | <1 |
| 378165 | Main Building - 2218 | Sink | Room 223 | 1 of 1 | Tap | left | <1 |
| 378166 | Main Building - 2218 | Sink | Room 223 | 1 of 1 | Water Fountain | right | <1 |
| 378168 | Main Building - 2218 | Sink | Room 225 | 1 of 1 | Water Fountain | right | <1 |
| 378170 | Main Building - 2218 | Sink | Room 227 | 1 of 1 | Water Fountain | right | <1 |
| 378621 | Main Building - 2218 | Sink | Room 123 | 1 of 1 | Water Fountain | right | <1 |
| 378622 | Main Building - 2218 | Fountain - Multi-Level | Across From Gym In Between Restrooms | 1 of 1. Higher fountain | Water Fountain | right | <1 |
| 378623 | Main Building - 2218 | Fountain - Multi-Level | Across From Gym In Between Restrooms | 1 of 1 | Water Fountain | right | <1 |
| 378628 | Main Building - 2218 | Sink | Room 207 | 1 of 2 | Water Fountain | right | <1 |
| 378632 | Main | Sink | Room 209 | 1 of 1 | Water | right | <1 |

| Sample ID | Building Name | Fixture Housing Type | Fixture Location | Fixture Location Details | Fixture Type | Fixture Position | Lead Test Result (ppb) |
|-----------|----------------------|-----------------------------|------------------|--------------------------|---------------------|------------------|------------------------|
| | Building - 2218 | | | | Fountain | | |
| 378634 | Main Building - 2218 | Sink | Room 211 | 1 of 1 | Water Fountain | right | <1 |
| 378636 | Main Building - 2218 | Sink | Room 213 | 1 of 1 | Water Fountain | right | <1 |
| 378638 | Main Building - 2218 | Sink | Room 215 | 1 of 1 | Water Fountain | right | <1 |
| 378654 | Main Building - 2218 | Fountain with Bottle Filler | Cafeteria | 1 of 1 | Water Bottle Filler | center | <1 |
| 378655 | Main Building - 2218 | Fountain with Bottle Filler | Cafeteria | 1 of 1 | Water Fountain | right | <1 |
| 378659 | Main Building - 2218 | Sink | Room 101 | 1 of 1 | Water Fountain | right | <1 |

EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: leadfreekids@doh.wa.gov